


# Lid Brace Arm Installation

Lid Brace Pad – (plate with nut & bolt ) drill 7/64 holes through the lid stainless steel skin and attach screws

Body Brace – drill 7/64 holes through kiln body stainless steel skin and attach screws



Lid Brace Arm – angle cut faces back of kiln. Unscrew nut on lid brace pad, insert the top of the lid brace arm through the body brace and through the lid brace pad. Insert hole in top of arm onto bolt and attach nut.

